

Aquarion Water Company
PFAS Sampling Results

Town/City: Darien

All Results Reported as parts per trillion (ppt)

Water System Name	Sample Location	Test Date	PFOA	PFOS	PFHpA	PFHxS	PFNA	TOTAL	Current	Other PFAS
								PFAS (5)	CT DPH	Tested
								Guideline	PFBS	
Darien	Post Road Station, Distribution Point	2019	5	ND	2	ND	ND	7	70	ND
	Springdale, Distribution Point	2019	4	ND	2	ND	ND	6	70	ND
	Rewak Well, POE - NOT IN SERVICE	2019	–	–	–	–	–	No Sample	70	–

Definitions:

ND - Not Detected

POE - point of entry. Sample collected after treatment as water enters the distribution system, before the first customer.