

**Aquarion Water Company**  
**PFAS Sampling Results**

**Town/City: Stamford**

All Results Reported as parts per trillion (ppt)

Water System Name	Sample Location	Test Date	PFOA	PFOS	PFHpA	PFHxS	PFNA	TOTAL	Current	Other PFAS
								PFAS (5)	CT DPH	Tested
								Guideline	PFBS	
Stamford	Stamford Reservoirs, POE	2019	4	ND	2	ND	ND	6	70	ND
	Woodway Road, Distribution Point	2019	4	ND	ND	ND	ND	4	70	ND
	Wire Mill Well, POE - <b>NOT IN SERVICE</b>	-	-	-	-	-	-	No Sample	70	-

**Definitions:**

**ND** - Not Detected

**POE** - point of entry. Sample collected after treatment as water enters the distribution system, before the first customer.